



Engineering & Application note

Issue Date: May '14

Subject: SMT Client v3.49 ReadMe

Relevant Products: SMT Client v3.49

Article Description

SMT Client v3.49 replaces v3.44 as the latest configuration software for the iSmart. All existing users are recommended to upgrade to the new software, all new users should install it from the outset.

This new version is essentially a service release; the new features are listed below.

Article Details

This update has fixed general bugs in the software. The latest firmware version is V3.80